

Health Canada Medical Device Recall Listing

Trade Name

- A) Rejuvenate Modular Neck, 0 DEG
- B) Rejuvenate Modular Neck, 8 DEG
- C) Rejuvenate Modular Neck, 16 DEG
- D) Rejuvenate SPT Modular Stem, Straight Press-Fit Texture TMFZ

Recall Posting Date

2012-05-28

Manufacturer

Howmedica Osteonics Corporation

Recall Start Date

2012-04-30

Recall Number

73679

Hazard Classification

Type II

Model or Catalog #

- A) NLS-300000B, NLS-340000B, NLS-380000B, NLS-420000B
- B) NLV-300800G, NLV-300800Y, NLV-340800G, NLV-340800Y, NLV-380800G, NLV-380800Y, NLV-420800G, NLV-420800Y
- C) NLS-301600P, NLS-341600P, NLS-3816000P, NLS-4216000P
- D) SPT-070000S, SPT-080000S, SPT-090000S, SPT-100000S, SPT-110000S, SPT-120000S

Lot or Serial #

- A) All lots
- B) All lots
- C) All lots
- D) All lots

Reason for Recall

Stryker Orthopedics has updated the instructions for use (IFU) for the Rejuvenate Modular Hip System. This is based on a reported rate of less than one percent for revisions potentially associated with fretting and/or corrosion at or about the modular neck junction.